

Pellet Mill	Enforcement Action (date)	Summary of Violation	Monetary Fine (if applicable)
Alabama Pellets (Drax) - Aliceville, AL  (formerly, Pinnacle Renewable Energy & Westervel Pellets)	<a href="#">Consent Order No. 22-051-CAP (Feb. 16, 2022)</a>	Emission Monitoring & Recordkeeping/Reporting - Failing to conduct required daily visual emission monitoring (22 days), record results of required daily monitoring, and maintain appropriate records	\$11,000
	<a href="#">Notice of Deviation (Sept. 18, 2018)</a>	Downtime of emissions control equipment	
	<a href="#">Consent Order No. 15-018-CAP (Dec. 3, 2014)</a>	Excess Emissions - Exceeded 250 tpy VOC emission limit (constructed a major source without PSD permit)	\$40,000
Alabama Pellets (Drax) - Demopolis, AL  (formerly, Pinnacle Renewable Energy)	<a href="#">Non-Compliance Form (June 30, 2022)</a>	Monitoring - Failure to collect samples from stormwater outfall during the monitoring report	
	<a href="#">Warning Letter (June 4, 2020)</a>	Best Mgmt Practices - Potential for uncontrolled discharges of sediment/pollutants into water from failing to fully implement/maintain BMPs; accumulated sediment observed downstream of facility  Document Deficiency - Permit application doesn't correctly identify relevant discharge points, etc.	
CM Biomass - Crossville, AL  (formerly, Mohegan Renewable Energy & Lee Energy Solutions)	<a href="#">Fine (July 24, 2020)</a>	OSHA - Workplace safety or health violation	\$5,506
	<a href="#">Fine (Feb. 20, 2020)</a>	OSHA - Workplace safety or health violation	\$11,470
	<a href="#">Notice of Violation (July 19, 2021)</a>	Exceeding maximum softwood feedstock limit and failing to report exceedance within 10 days	
	<a href="#">Consent Order No. 20-027-CAP (Dec. 12, 2019)</a>	Excess Emissions - Exceeded VOC emission rate from dry hammermill and pelletizing system / failed stack test	\$40,000
	<a href="#">Consent Order No. 16-023-CAP (Dec. 29, 2015)</a>	Excess Emissions - Exceeded PM emission rate from dryer	\$60,000
	<a href="#">Notice of Violation (Feb. 19, 2015)</a>	Improper Operation - Exceeded the annual limitation on hours of operation	
	<a href="#">Warning Letter (Nov. 3, 2014)</a>	Fugitive Dust - Accumulated wood dust noticed during inspections, impacted neighboring properties	
	<a href="#">Warning Letter (Nov. 1, 2013)</a>	Fugitive Dust - Excess PM emissions / wood dust, impacted neighboring property	
	<a href="#">Warning Letter (Aug. 22, 2011)</a> <a href="#">Notice of Violation (July 2, 2009)</a>	Unreported permit deviations Failure to maintain records of weekly emission monitoring Commencing construction without a permit	
Highland Pellets - Pine Bluff, AR	<a href="#">Consent Administrative Order LIS No. 20-189 (Nov. 30, 2020)</a>	Improper Operation - Failure to maintain minimum bark burner temperature due to drying process being aborted  Unpermitted Activity - Creation and repeated use of wood waste arbor pile and associated emission sources without permit; constructed and operated green wood chip storage inconsistent with permit; operated second heater baghouse without permit  Recordkeeping / Monitoring Deficiencies - Failure to perform and record weekly equipment inspections and related monitoring activities	\$47,760
	<a href="#">Fine (Nov. 27, 2018)</a>	OSHA - Workplace safety or health violation	\$16,707
	<a href="#">Consent Administrative Order LIS No. 18-065 (July 26, 2018)</a>	Unpermitted Activity - Installed and operated 11 unpermitted sources, including green hammermills, heater baghouses, diesel and gasoline tanks  Reporting - Failed to timely submit semi-annual monitoring report	
Enviva Pellets - Cottdale, FL	<a href="#">Consent Order # 22-1925 (22-1925) (Aug. 3, 2022)</a>	Stack Test - Failed to test RTO/RCO to demonstrate compliance with PM10 and PM2.5 emission limits within the scheduled required by the permit (90 days)	\$8,000
	<a href="#">Consent Order # 20-0914 (May 20, 2020)</a>	Compliance Report - Failure to timely submit compliance report	\$1,125
	<a href="#">Consent Order # 18-1106 (July 17, 2018)</a>	Emissions Exceedance, Reporting Violation, Improper Operations - Failing to notify DEP of temp inability to comply with permit condition, failed to reduce pelletizing line processing rate when one dryer was not operational, unauthorized emissions on 8 days, failed to timely submit semi-annual monitoring report, failed to submit statement of compliance	\$10,500
	<a href="#">Consent Order # 17-1134 (Nov. 15, 2017)</a>	Incomplete Application & PSD Avoidance - Application failed to include accurate identification of VOC emission levels, which would have subjected the facility to PSD review; information needed to determine BACT; and air quality impact of proposed modification	\$3,250
	<a href="#">Consent Order # 15-0416 (Sept. 11, 2015)</a>	Monitoring Deficiencies - Failure to install and operate appropriate monitoring system for PM emissions, opacity, and PM control technology	\$4,500
Hazlehurst Wood Pellets (Fram) - Hazlehurst, GA	<a href="#">Enforcement Order EPD-AQC-7264 (Apr. 14, 2023)</a>	Control Technology - Failing to operate WESP/RTO at all times when wood-fired burner and dryer were in operation; failing to operate controls properly (temp); failing to timely report deviations / excursion; violations of semi-annual report requirements (failing to report amount of wood dried; pellets produced)	\$51,722
	<a href="#">Fine (Sept. 7, 2021)</a>	OSHA - Workplace safety or health violation	\$11,421
	<a href="#">Fine (Dec. 12, 2020)</a>	OSHA - Workplace safety or health violation	\$13,653
	<a href="#">Fine (May 6, 2015)</a>	OSHA - Workplace safety or health violation	\$9,500

Pellet Mill	Enforcement Action (date)	Summary of Violation	Monetary Fine (if applicable)
Archer Forest Products (Fram) - Nahunta, GA	<a href="#">Enforcement Order EPD-AQC-6965 (June 5, 2019)</a>	Excess Emissions - Potential emissions exceedances for VOC, CO, single HAPs, combined HAPs  Other Violations - Potential exceedance of annual drying limit; failing to conduct timely performance test	
	<a href="#">Fine (Apr. 13, 2022)</a>	OSHA - Workplace safety or health violation	\$6,598
	<a href="#">Fine (Dec. 29, 2021)</a>	OSHA - Workplace safety or health violation	\$7,252
Telfair Forest Products (Fram) - Lumber City, GA	<a href="#">Enforcement Order EPD-AQC-7159 (Mar. 2, 2022)</a>	Performance Tests - Failure to submit performance tests, test plans, and certifications related to tests	\$5,000
	<a href="#">Enforcement Order EPD-AQC-6931 (Nov. 2, 2018)</a>	Improper Operation - Exceeded limit for drying of green wood shavings; excess downtime and temperature excursions for dryers	\$6,000
	<a href="#">Fine (Aug. 29, 2018)</a>	OSHA - Workplace safety or health violation	\$6,338
	<a href="#">Enforcement Order EPD-AQC-6796 (May 12, 2017)</a>	Excess Emissions - Exceeded PM emissions levels  Other Violations - Failure to provide relevant data in performance test report; using monitoring instruments to fine tune burners before testing	\$21,938
	<a href="#">Fine (Apr. 14, 2016)</a>	OSHA - Workplace safety or health violation	\$19,205
	<a href="#">Enforcement Order EPD-AQC-6747 (Sept. 23, 2014)</a>	Excess visible emissions	\$14,584
	<a href="#">Enforcement Order EPD-AQC-6558 (Dec. 7, 2012)</a>	Excess Emissions - Exceeded opacity emissions limits; potential excess emissions of CO & VOCs	\$3,125
Appling County Pellets (Fram) - Baxley, GA	<a href="#">Enforcement Order EPD-AQC-6965 (June 5, 2019)</a>	Excess Emissions - Potential emissions exceedances for VOC, single HAP, combined HAPs, CO  Other Violation - Potential exceedance of annual drying limit	
	<a href="#">Enforcement Order EPD-AQC-6829</a>	Excess Emissions - Exceeded emission limits for PM and VOCs	\$5,000
	<a href="#">Fine (Aug. 27, 2013)</a>	OSHA - Workplace safety or health violation	\$7,000
	<a href="#">Fine (Aug. 21, 2013)</a>	OSHA - Workplace safety or health violation	\$51,000
LJR Forest Products - Swainsboro, GA	<a href="#">Enforcement Order EPD-AQC-7137 (Nov. 30, 2021)</a>	Failure to submit complete and accurate permit amendment application	\$12,500
	<a href="#">Enforcement Order EPD-AQC-6762 (Dec. 9, 2014)</a>	Construction of modification without permit and failure to conduct performance testing  Improper Operation - Failure to vent hammermills, pellet coolers, and aspirator to burner	\$5,000
	<a href="#">Fine (Dec. 9, 2013)</a>	OSHA - Workplace safety or health violation	\$10,960
Enviva Pellets - Waycross, GA (formerly, Georgia Biomass)	<a href="#">Enforcement Order EPD-AQC-6566 (Mar. 4, 2013)</a>	Emissions Exceedance - Exceeded legal emission limits for VOCs; constructed a PSD major source without a permit	\$100,000
Drax - Bastrop, LA (Morehouse Facility)	<a href="#">Settlement No. SA-AE-22-0039 (2022)</a>	Excess Emissions - Exceeded legal emission limits for VOC and various HAPs (formaldehyde, methanol, acetaldehyde) on multiple occasions  Other Permit Violations - Exceeding annual hours of operation of Fire Pump Engine; failure to use/maintain control devices in proper working order; exceeded annual pellet production rate	\$1.6 million
	<a href="#">Settlement No. SA-MM-19-0065 (2020)</a>	Excess Emissions - Exceeded emission limits for SO2, VOCs, and HAPs (methanol, formaldehyde, acetaldehyde) (2016 Compliance Order)  Other Violations - Failure to meet opacity monitoring requirements (2016 Compliance Order); several unpermitted emission sources (2016 Compliance Order); unregistered access to radioactive material - soil density gauge (2018 Compliance Order)	\$20,000
Drax - Urania, LA (LaSalle Facility)	<a href="#">Settlement No. SA-MM-22-0040 (2022)</a>	Excess Emissions - Exceeded legal emission limits for VOC and various HAPs (formaldehyde, methanol, acetaldehyde) on multiple occasions  Other Permit Violations - Exceeding annual hours of operation of Fire Pump Engine; failure to use/maintain control devices in proper working order; exceeded annual pellet production rate	\$1.6 million
	<a href="#">Fine (Dec. 12, 2018)</a>	OSHA - Workplace safety or health violation	\$18,564
Drax - Gloster, MS (Amite Facility)	<a href="#">Notice of Violation (Mar. 14, 2023)</a>	Excess Emissions - HAPs emissions exceeded the legal limit for individual HAPs (formaldehyde and methanol at 9 tpy) and total HAPs (25 tpy) since January 2021	
	<a href="#">Agreed Order No. 7082 20 (Nov. 4, 2020)</a>	Excess Emissions - VOC emissions exceeded the legal limit (249 tpy) since 2016	\$2.5 million + \$80,000/month until new controls installed
	<a href="#">Agreed Order No. 6959 19 (July 1, 2019)</a>	Improper Operation - Exceeded annual hour limit for non-emergency use of fire pump engine since August 2015  Recordkeeping - Failure to specify between emergency and non-emergency use of fire pump engine for 2 years; late submittal of semi-annual report  Monitoring Deficiency - Failure to conduct visible emission evaluation; no certified monitor employed	\$110,000
Enviva Pellets - Amory, MS	<a href="#">Fine (Oct. 25, 2019)</a>	OSHA - Workplace safety or health violation	\$31,500
	<a href="#">Agreed Order No. 7020 20 (Jan. 21, 2020)</a>	Stormwater Permit - Failed to obtain coverage under Mississippi Baseline Stormwater General Permit	\$10,000
	<a href="#">Notice of Deficiency (July 12, 2017)</a>	Recordkeeping Deficiencies - Related to watering truck and dust observation logs from May 2016 through April 2017	
	<a href="#">Notice of Violation (Mar. 14, 2017)</a>	Title V - Late submission of Annual Compliance Certification	



Pellet Mill	Enforcement Action (date)	Summary of Violation	Monetary Fine (if applicable)
Enviva Pellets - Ahoskie, NC	<a href="#">Notice of Violation (July 21, 2016)</a>	Improper Operation - Malfunction of emission control technology for dryer (WESP), led to operation of the dryer for extended time (31 days) without controls; failure to notify of malfunction  Improper Operation - Operation of emission control technology (WESP) below minimum requirements for extended periods (23 and 46 days)	
	<a href="#">Notice of Violation (May 2, 2013)</a>	Excess Emissions - Emissions control technology for dried wood silo (bin filter) circumvented due to broken door, allowed for excess particulate emissions  Fugitive Dust - Deficiencies in fugitive dust plan led to observable road dust and sawdust in air leaving property	
Enviva Pellets - Sampson, NC	<a href="#">Civil Penalty Assessment Case No. 2020-065 (Jan. 26, 2021)</a>	Improper Operation - Failure to meet minimum operating requirements for pollution control technologies (RTO and RCO temps) (83 violations)	\$7,377
	<a href="#">Special Order by Consent 2020-004 (Dec. 16, 2020)</a>	Excess Emissions - Exceeded BACT emissions limit for PM and PM10	\$59,000
	<a href="#">Settlement Agreement (May 31, 2019)</a>	Permit Application Deficiency - State concluded that Enviva's application was deficient because it failed to include available pollution control technology for hazardous air pollutants (improper case-by-case MACT analysis); additional pollution controls to be installed subject to Settlement	
	<a href="#">Civil Penalty Assessment Case No. 2018-002 (Mar. 5, 2018)</a>	Excess Emissions - Exceeded BACT emission limit for CO (NOV also noted excess VOC emissions)	\$5,333
	<a href="#">Special Order by Consent 2018-003 (Sept. 21, 2018)</a>	Excess Emissions - Exceeded BACT emission limit for VOCs from dryer	
	<a href="#">Notice of Violation (Feb. 3, 2017)</a>	Recordkeeping Violations - Failure to maintain records of monthly visible emissions monitoring	
Enviva Pellets - Hamlet, NC	<a href="#">Notice of Violation (Dec. 21, 2022)</a>	Improper Operation - Failure to meet minimum operating requirements for pollution control technology (RTO temp)	
	<a href="#">Civil Penalty Assessment Case No. 2020-066 (Jan. 26, 2021)</a>	Improper Operation - Failure to meet minimum operating requirements for pollution control technologies (RTO and RCO temps) (115 violations)	\$11,197
	<a href="#">Fine (Dec. 30, 2021)</a>	OSHA - Workplace safety or health violation	\$22,900
Enviva Pellets - Northampton, NC	<a href="#">Notice of Deficiency (Dec. 7, 2016)</a>	Failure to submit permit renewal application	
	<a href="#">Notice of Deficiency (Aug. 22, 2014)</a>	Failure to submit semiannual report	
	<a href="#">Notice of Violation (Nov. 21, 2022)</a>	Excess Emissions - Exceeded formaldehyde emissions limit	
Active Energy Renewable Power - Lumberton, NC (project cancelled)	<a href="#">Notice of Violation (May 5, 2021)</a>	Construction of equipment without a permit	
Enviva Pellets - Greenwood, SC	<a href="#">Consent Order 20-003-A (July 17, 2020)</a>	Recordkeeping & Monitoring Deficiencies - Failure to maintain records, document corrective actions, conduct required monitoring and maintenance	
		Control Technology - Failure to limit pollution control bypass stack other than during emergency or mechanical failure  Other Violations - Failure to limit opacity to required level on two occurrences	\$13,000
Jasper Pellets - Jasper, SC	<a href="#">Consent Order 21-001-A (Jan. 2021)</a>	Construction of equipment without a permit and failure to report to DHEC that construction commenced	\$15,000
Woodville Pellets - Woodville, TX	<a href="#">Agreed Order Docket No. 2020-0449-AIR-E (Apr. 8, 2022)</a>	Excess Emissions - Exceeded VOC emissions limits; Failed to install control technology (RTO) and operated dry hammermill and cooler system without routing emissions to pollution control for combined 18 months	\$517,068
		Other Violations - Failed to submit permit compliance certification, renewable application for Federal Operating Permit and operated prior to obtaining permit, failure to report on emissions deviations, failure to maintain valves and equipment to prevent flow from furnace bypass	
	<a href="#">Fine (Feb. 7, 2022)</a>	OSHA - Workplace safety or health violation	\$82,180
	<a href="#">Fine (Oct. 13, 2021)</a>	OSHA - Workplace safety or health violation	\$12,288
Enviva Pellets - Southampton, VA	<a href="#">Fine (Mar. 2, 2020)</a>	OSHA - Workplace safety or health violation	\$16,920
	<a href="#">Fine (Apr. 11, 2023)</a>	OSHA - Workplace safety or health violation	\$16,020